# DEQ SITE ASSESSMENT PROGRAM - STRATEGY RECOMMENDATION

Site Name: Fred Devine Diving & Salvage, Inc.

**Site CERCLIS Number**: (none)

DEQ ECSI Number: 2365

Site Address: 6211 N. Ensign Street

Portland, Oregon 97217

Recommendation By: Tom Gainer, Voluntary Cleanup and

Site Assessment Section, DEQ Northwest

Region

Approved By: Michael E. Rosen, Portland Harbor

Manager, DEQ Northwest Region

Date: September 21, 1999

NOTE: This site (Figures 1 and 2) is within a 6-mile stretch of the Lower Willamette River in which the U.S. Environmental Protection Agency (EPA) conducted a sediment study in 1997. This area, referred to as the Portland Harbor, is between the upstream ends of Sauvie Island (River Mile 3.5) and Swan Island (RM 9.5). The purpose of this Strategy Recommendation is to determine whether a specific hazardous substance release or a specific past operation at the site can be linked to contamination documented by EPA in sediments adjacent to the site. Because of this focus, the Strategy Recommendation may omit some historical site information, regulatory issues, or further-action conclusions that might otherwise be included in a DEQ Strategy Recommendation.

# Background, Portland Harbor Sediment Evaluation

In September and October 1997, EPA's contractor, Roy F. Weston, Inc., collected 187 near-shore sediment samples within the Portland Harbor area defined above. Most samples (150) were collected as shallow grab samples within the upper 6 to 17 centimeters (cm) of sediments. 37 deeper composite core samples, from depths of between 55 and 139 cm, were also collected. All samples were analyzed for total metals, semi-volatile organic compounds (SVOCs), total organic carbon (TOC), and sediment grain size. Selected samples were also variously analyzed for organotins (TBTs), pesticides,



'polychlorinated biphenyls (PCBs), chlorinated herbicides, and polychlorinated dioxins and dibenzofurans.

Based on analytical results from this study, which showed extensive sediment contamination, EPA is currently considering Portland Harbor for inclusion on the federal National Priority List (NPL - also known as Superfund).

Between late 1998 and mid-1999, DEQ examined EPA's analytical data to determine potential sources for sediment contamination in the Harbor. Potential sources associated with the most contaminated areas of sediment were sites already active in DEQ's Cleanup Programs.

DEQ categorized other areas of sediment contamination (i.e., those areas not thought to be associated with active Cleanup Program sites) by defining the areas:

- having the highest detected concentration of a given contaminant;
- with contaminant concentrations in the upper five percent of a given contaminant's detected concentrations; and
- having contaminant concentrations above an apparent "baseline range" most commonly detected throughout the harbor area.

DEQ categorized in this manner because there are no established freshwater sediment contaminant concentration guidelines or well-defined background contaminant concentrations for the harbor area. The contaminant "baseline range" was developed by examining the geometric distribution of concentrations for each contaminant detected. Any sediment concentrations that appeared to depart significantly from the ranges most commonly detected were suspected of lying near a potential contaminant source.

A shallow and subsurface sediment sample (SD136 and SD136-C, respectively) were collected adjacent to the southeastern boundary of the Devine facility, which is also in the vicinity of the City of Portland Ensign Street stormwater outfall (Figure 3). As shown on Table 1, the shallow sample, SD136, had concentrations of cadmium, copper, zinc, bis(2-ethylhexyl)phthalate, and butylbenzylphthalate that exceeded baseline levels. The subsurface sample, SD136-C, had concentrations of cadmium and di-n-butylphthalate that exceeded baseline levels.

It appears that the Devine site could have contributed towards the metal and phthalate contamination detected at sample location SD136 based on their site activities. Since the stormwater drainage

pipeline is shared with other properties in the area that could contribute contaminants to stormwater drainage or directly to the river, Devine's potential contribution to sediment contamination observed at SD136 is unclear.

The Port of Portland and Cascade General, Inc. conducted a sediment investigation of the Portland Shipyard and issued a report in November 1998 that contained additional sediment data. One of their sampling locations, PSY12, was on the north side of the Devine dock (Figure 3). As shown on Table 1, shallow sample PSY12 had concentrations of arsenic, copper, zinc, bis(2-ethylhexyl)phthalate, and low- and high-molecular weight polynuclear aromatic hydrocarbons (LPAHs and HPAHs, respectively) that exceeded baseline levels. Their sample at the Devine dock was identified as one of the highest "hot spots" for PAHs in the Portland Shipyard. As shown on Figures 4 and 5, the Devine dock appears to be the source of PAH contamination.

One shallow sediment sample (SD129) was collected about 1,000 feet northwest of the Devine facility, adjacent to the U.S. Coast Guard dock. Contaminant concentrations in sample SD129 that exceeded Portland Harbor baseline concentrations include: barium, cadmium, copper, iron, lead, mercury, zinc, 4-methylphenol, bis(2-ethylhexyl)phthalate, butylbenzylphthalate, di-n-butylphthalate, and HPAHs. However, of these contaminants, only concentrations of copper, zinc, 4-methylphenol, bis(2-ethylhexyl)phthalate, butylbenzylphthalate, and di-n-butylphthalate are significantly elevated above Portland Harbor baseline concentrations (by greater than 10%). Although there are many similar contaminants downstream at SD129 as in SD136, there is no clear link between the Devine facility and downstream sediment contamination.

## Operational History

The following site history was summarized primarily from a Phase I Environmental Assessment (July 17, 1992) and Update (December 4, 1995) prepared for Devine. Fred Devine Diving & Salvage started operations in 1975 and was the first occupant of the 5.7-acre site. A detailed description of Devine's on-site activities was not available for this Strategy Recommendation.

Pacific Coast Environmental, Inc. operated an industrial cleaning and hazardous waste transportation business as a tenant on the subject property from about 1988 to 1995. They used two above ground tanks for diesel fuel and stored tanks, drums, and wastewater from tank cleaning operations prior to off-site disposal. A floor drain in their portion of the warehouse was connected to an oilwater separator and discharged to "the sewer system." It is not clear whether the above ground tanks are still on site and in use.

Portland Steam Navigation Co. leased office and dock space starting around 1987 and operated the river excursion boat "Portland Rose" from the site.

Aerial photographs show the property was undeveloped in 1963 and was a wetland in 1936.

## Regulatory History

## Spills

On March 10, 1999, a 1000 by 400-foot petroleum sheen was observed in the river originating at the storm sewer outfall at the base of Ensign Street adjacent to the Devine site (OERS #99-696). The storm sewer drains multiple properties, including the Devine property, and a spill source was not determined.

A 500 by 35-foot petroleum sheen was observed at the same outfall location on June 24, 1980, and a spill source was not determined.

### Underground Storage Tanks

Two 2,000-gallon and one 4,000-gallon gasoline underground storage tanks (USTs) were removed from the subject site in April 1993. DEQ records indicate that the three tanks had not leaked and that the tank closures were clean.

#### Hazardous Waste

Pacific Coast Environmental operated as a hazardous waste generator (ORR000000612) until 1995. A complaint was received by the DEQ in March 1995 concerning possible dumping of hazardous materials (just prior to the company going out of business). A subsequent DEQ site visit found no violations but noted "suspicious disposal procedures."

## Water Quality

The facility does not have a water/stormwater discharge permit.

### Site Hydrogeology

The site lies in the northern-most Portland Basin, a major north-southeast trending sediment filled structural depression found in the northern part of the Willamette River valley and adjoining Columbia River valley (Swanson et al, 1993). The basin is filled with recent alluvium, Pleistocene cataclysmic flood deposits, Miocene to Holocene nonmarine sedimentary rocks, and is underlain by Eocene to Miocene volcanic and sedimentary rocks that are exposed along the basin margins.

The youngest deposits are recent alluvium (silt, sand and gravel mixtures) characteristic of an active fluvial environment. These are made up of shoreline, river channel, and adjacent floodplain deposits.

Terraces that rise 50 to 100 feet above the northeastern shore of the Willamette were formed during Pleistocene cataclysmic flooding related to glacial Lake Missoula, and consist of unconsolidated mixtures of silt, sand, and gravel that generally are coarser than the recent deposits. Fill comprised of fine to medium sands and silt was also placed in many areas along the river during site development. The total thickness of recent alluvium and flood deposits appears to be about 100 feet in the vicinity of the site.

Coarse gravel to conglomerate of the Troutdale Formation, deposited by the ancestral Columbia River, underlies the cataclysmic flood deposits and appears to be about 100 feet thick in the vicinity of the site. Sandy River mudstone underlies the Troutdale Formation and appears to be about 100 feet thick. Basalt of the Columbia River Basalt (CRB) group forms the basement rock of the Portland Basin, and may be as much as several hundred feet thick in the vicinity of the site.

Aquifers in the unconsolidated sedimentary deposits generally are unconfined and localized due to heterogeneity of the deposits. The Troutdale Formation is an important regional aquifer and is widely tapped for both potable and non-potable uses. Interbedded Claystone and/or siltstone, or cementation often promotes confined aquifer conditions within the Troutdale Formation. Deep wells installed in fractured CRB can be very productive and important supply wells. Site elevation is about 30 feet above mean sea level.

# Pathway Summary

The Devine facility lies in an area of mixed industrial and commercial use. There are no residences within 1/4 mile of the facility.

Utility trench workers could potentially be exposed to any potential subsurface contaminants through direct contact, inhalation, or incidental ingestion.

Oregon Water Resources Department has no well logs for domestic wells within one mile of the subject site.

The nearest significant wetland is located approximately five miles downstream at the mouth of Multnomah Channel. Cathedral Park is located approximately two miles downstream of the subject site.

Both recreational and subsistence fishing occur within the Lower Willamette River. Commercial fishing within the Portland Harbor is limited to a small Pacific lamprey fishery. Recreational boating, water skiing, swimming, and beach use also occur within the Harbor.

The Lower Willamette River provides habitat for 39 fish species, including populations of wild cutthroat trout, rainbow trout, and mountain whitefish. White sturgeon are plentiful within the Harbor. The Harbor is also an important migratory corridor, nursery habitat, and adult foraging area for two runs of chinook salmon, two runs of steelhead trout, and individual runs of coho and sockeye salmon.

Upper Willamette River populations of chinook and steelhead, which migrate through the Harbor, are listed as threatened species under the Federal Endangered Species Act. The Pacific lamprey is considered a federal species of concern.

Great blue herons, cormorants, osprey, mergansers, kingfishers, peregrine falcons, and bald eagles routinely forage within the Harbor. The area is also part of the wintering range for the Aleutian Canada goose. All are protected under the Migratory Bird Treaty Act. The peregrine falcon is federally listed as an endangered species, while the Aleutian Canada goose is federally listed as threatened species. The bald eagle also is a threatened species, but was recently proposed to be removed from this list.

There is little data on the nature and extent of the benthic community within Portland Harbor sediments. However, it is known that contamination in the benthos, which is a protected beneficial use, can be the source of food-chain effects that radiate up to the species listed above, including humans.

The Lower Willamette River is water quality limited for the following toxic compounds:

- Dioxins/furans (water column and sediments);
- Mercury (fish tissue);
- Pesticides (water column and sediments);
- Polynuclear Aromatic Hydrocarbons PAHs (water column and sediments); and
- Trace metals (water column and sediments).

DEQ's Water Quality Division is developing Total Maximum Daily Load requirements (TMDLs) within the lower Willamette River for these contaminants. A TMDL for 2,3,7,8-TCDD was established in 1991.

## Conclusions/Recommendations

**NOTE**: As indicated previously, this review is limited to establishing a link between site activities and contamination in adjacent Portland Harbor sediments. It does not necessarily represent a thorough review of available site data, and the conclusions and recommendations presented below may reflect this limited focus.

The following conclusions are based on the contents of this review:

- Site activities may have contributed towards sediment contamination adjacent to the site. Moderately elevated concentrations of sediment contaminants adjacent to the site near the city stormwater outfall (cadmium, copper, zinc, bis(2-ethylhexyl)phthalate, and butylbenzylphthalate, and di-n-butylphthalate) are potentially consistent with current and historical site activities. The source of contaminants is not clear because the sediment sample was collected in the vicinity of a city stormwater outfall that collects stormwater from multiple properties, including the subject property.
- The current and historical use of the site's dock, possibly for conveyance of materials and boat fueling and maintenance, appears to be a source of sediment contamination by routine or accidental activities. A sediment sample collected adjacent to the site dock showed elevated levels of arsenic, copper, zinc, and PAHs. The PAH sediment concentrations were particularly high, showing as a hot spot within the Portland Shipyard with the Devine dock appearing as the contaminant source.
- Additional possible migration pathways resulting in sediment contamination from the site include stormwater runoff directly to the river or into the city stormwater sewer.

Contamination of river sediments in the vicinity of the Devine site may represent a threat to human health and aquatic life within the river. The specific nature and significance of these threats cannot be determined without further characterization and delineation of contamination in groundwater, subsurface soil, and sediments. A Remedial Investigation (RI) is required to evaluate the potential ecological threat of the sediment contamination. It is recommended that once the full character and extent of site sediment contamination has been determined, a Risk Assessment, including sediment bioassays and bioaccumulation assessment, be conducted. DEQ has determined that these actions warrant a high priority for follow-up.

There is insufficient information to propose adding the site to DEQ's Confirmed Release List or Inventory.

# References

DEQ consulted the following general references in preparing this Strategy Recommendation:

- 1. Portland Harbor Sediment Investigation Report, prepared by Roy F. Weston, Inc. for USEPA, May 1998.
- Phase I Environmental Assessment, prepared by Marine & Environmental Testing, Inc. for Fred Devine Diving & Salvage, Inc., July 17, 1992.
- 3. Phase I Environmental Assessment Update, prepared by Marine & Environmental Testing, Inc. for Fred Devine Diving & Salvage, Inc., December 4, 1995.
- 4. Portland Shipyard Sediment Investigation, prepared by Striplin Environmental Associates, Inc. for Port of Portland and Cascade General, Inc., November 9, 1998.
- 5. DEQ LUST Database.
- 6. DEQ HWIMSy Hazardous Waste Generator Database.
- 7. DEQ SPINS Spill Database.
- 8. MetroScan Property Records, Multnomah County, Oregon.

## Attachments

Table 1: River Sediment Contaminant Concentrations

Figure 1: Site Location Map

Figure 2: Site Property Boundary Map

Figure 3: Sediment Sampling Points, 1997 Portland Harbor Sediment Investigation

Figure 4: Contours of 0-4 ft Surface Total LPAH Concentrations in the Vicinity of the Portland Shipyard

Figure 5: Contours of 0-4 ft Surface Total HPAH Concentrations in the Vicinity of the Portland Shipyard

TABLE 1


River Sediment Contaminant Concentrations (1997)


Fred Devine Diving and Salvage Co.


					П	Apparent
			Fred Devine			Portland Harbor Sediment
		Northwest	[1	ng and Sal	P.	Baseline
Contaminant	Units	SD129	PSY12	SD136	SD136-C	Maximum Value
•				٠.		42800 5 <sup>2,71</sup>
Aluminum	ppm	38600	NA	15400	29200	
Antimony	ppm	<6	0.6	<7	<4	<5 _
Arsenic	ppm	<6	17	<7	<4	ر5 · ل
Barium	ppm	19,7	NA	138	168	195 —
Beryllium	ppm	0.7	NA	0.3	0.5	0.7 7
Cadmium	ppm	0.7	0.4	1	0.8	0.6
Chromium	ppm	41 /	17	25	40	41 27
Cobalt	ppm _	18	NA	13	. 16	19.7 —
Copper	ppm	,131	119	82	43	60 34 30
Iron	ppm	47300	NA	37900	35400	45000 301 (30
Lead	ppm	38	27	24	27	30 17
Manganese	ppm	698	NA .	323	431	810 1,500
Mercury	ppm	0.16	<0.05	0.06	0.04	0.1 د ۱۹
Nickel	ppm	29	18	20	25.	32 21
Selenium	ppm	15	NA	10	9	15 🔷
Silver	ppm	1.4	0.2	. 0.9	0.9	1.4
Thallium	ppm .	11 -	NA '	<7	4	13 -
Titanium	ppm	NA	NA	NA .	NA .	2075 —
Vanadium	ppm	108	NA .	69	90	112 -
Zinc	. ppm	279	264	178	116	118 9 2
2-Methylnaphthalene	ppb	26	20	<19	<19	150
4-Methylphenol	ррь	1100	ŅΑ	380	<19	680
Benzoic Acid	ррь	<190	, NA	<,190	<190	<200
Benzyl Alcohol	ррь	<19	NA	<19	<19	<20
bis(2-Ethylhexyl)phthalate	ppb	760	440	2100	370	. 390
Butylbenzylphthalate	. ppb	74	<10	62	<19	<20
Carbazole	ppb	25	NA	<19	<19	100
Di-N-Butylphthalate	ррь	51	<10	<19	44	<20
Di-N-Octylphthalate	ppb	<19	13	<19	<19	<20
Dibenzofuran	ppb	20	26	<19	<19	100
Dimethylphthalate	ppb	· <19 .	<10	19	<19	<20
Pentachlorophenol	ррь	<96	<100	<96	<97	Detect
Phenol	ppb	<19	<50	<19	<19	<20
LPAHs (total)	ppb	433	2433	129	61	700
HPAHs (total)	. ppb	2474	17268	1025	577	2400
DDTs (total)	ppb	· NA	<6	. NA	NA H	220
PCBs (total)	ррь	NA	57	NA	NA	<180
Organotins (total)	ppp	· NA	NA NA	NA .	NA	300
2,4-D	PPD	NA NA	NA	· NA	, NA	<3.3
2,4-DB	ppb	NA NA	NA NA	NA .	NA NA	<5
TOC	%	1.8	1	1.5	1.3	2
	, -		1			-
<b>5</b>				·		
Water Depth	Ft	31		20	20	
Sediment Sample Depth	cm	0-10	0-10	0-10	0-90	~
		•				


NA = not analyzed


PSY sample data from Portland Shipyard (November 9, 1998)











# OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY SITE ASSESSMENT ACTION - Northwest REGION

Facility Name: Fred Devine Diving > Salvage Inc.	ECSI #: 2365
Address: 6211 N. Ensign St.	
PRIL	<u> </u>
Company: Fred Devine Diving & Solvage, Inc.  Name  T. Leitz	Phone: 503-283-528
Address 6211 N. Ensign St. Portland, OR 97217	- ·
Action Date: 8/3(/99	
Report Type: Strategy Lecommendation	
Preliminary Assessment:	
State Federal Voluntary	PAE XPA
Screening:	
X State Federal Spill	
Note: Spill screenings may not require Strat	egy Recommendation
Recommended Action:	
NFA [Need management approval]	
Add to CRL	
Add to Inventory	
High PriorityRequires immediate respo	nse
V Other Describe: High priority RI	
Report Writer: Tom Gainer	
<u>Headquarters</u>	EPA Other
Transmittal Date(s):	
Report Supplement(s):	
	rating
	<u>lans</u> <u>Other</u>
Supplemental Date(s):	
Checklist:	
✓       Strategy Recommendation       Letter to RP         ✓       Data (if applicable)       Spill Report         Site Report       Site Report	SAPS * Map (if applicable)
Manager's approval:	

#### **DISCUSSION:**

Discuss your overall impression of the threat posed by the site. Include brief discussion of major factors such as potential or known releases, waste quantity, human and environmental targets, and use of nearby groundwater or surface water. Also discuss any important factors or considerations not addressed in the SAPS scoresheet. Discuss whether you feel the SAPS score generated for the site reflects the overall threat posed by the site to the surrounding population and environment.

The following contaminants were elevated above fortland that bor baseline concentrations in sediment samples collected adjacent to the subject site: arsenic, condmium, copper, zinc, bis (2-Ethylheryl) phthalate, butylbenzyl phthalate, di-n-butyl phthalate, and low- and high-molecular weight polycyclic aromatic hydrocarbons (LPAHs and HPAHs, respectively). The subject site may have contributed towards sediment contamination near the city stormwater outfall and appears to be the primary source of highly elevated PAH contamination adjacent to the facility's dock.

# **RECOMMENDATION:**

<b>K</b>	Further Action - High Priority	
	Further Action - Medium Priority	
	Further Action - Low Priority	
	No Further Action	
	Refer To	_ for further consideration
	Other:	

#### LISTING RECOMMENDATION

	•
	Recommend proposal on Confirmed Release List
Π.	Recommend proposal on Inventory
- <b>X</b>	Insufficient information to list on the Confirmed Release List
图	Insufficient information to list on the Inventory
	Excluded from listing